

**Watchtree Nature Reserve**  
 Great Orton, Carlisle, CA5 6NL  
**Location: Watchtree Wheelers**

<b>Title :</b> Berg 142 2 Seater	<b>Date of Assessment :</b> 30/07/2018	<b>Risk Assessor :</b> Matthew Wind
<b>Risk Assessment Reference :</b> RA 60	<b>People involved in making this assessment :</b> Matthew Wind	
<b>Task/ Process :</b> Safe use of Berg 142 2 seaters	<b>People at Risk :</b> Employees, Members of the Public, Volunteers, Service Users, Children & Young Persons, Visitors	

<b>Hazard : Manual handling</b> Large heavy equipment could cause muscle or skeletal damage if handled incorrectly.
<b>Control Measures:</b>
1. Only roll the Berg into and out of the cycle storage unit in accordance with it's turning circle.
2. move other smaller bikes out of way to create space to walk around all areas of the equipment
3. do not attempt to lift Berg over any obstacle due to it's weight, instead move obstacle or go round it

<b>Hazard : Mechanical</b> Potential for getting fingers caught in moving parts - chain.
<b>Control Measures:</b>

<b>Hazard : Repetitive Movements</b> Muscle and soft tissue damage due to overuse of same muscle groups in prolonged activity
<b>Control Measures:</b>
1. Observe correct position on cycle and adjust as necessary, and general fitness of rider
2. Watchtree staff to recommend a suitable ride route for the rider and service user

<b>Hazard : Public or Visitor Access</b>
<b>Control Measures:</b>

<b>Hazard : Uneven, Wet or Slippery Floors</b>
<b>Control Measures:</b>

<b>Hazard : Vibration</b>
<b>Control Measures:</b>

<b>Documents Associated with this Risk Assessment:</b>	
<b>Review Date :</b> 18/08/2020	<b>Reviewer :</b> Dan Dan