

Watchtree Nature Reserve
 Great Orton, Carlisle, CA5 6NL
Location: Compost Toilet

Title : Compost Toilet	Date of Assessment : 04/10/2018	Risk Assessor : Ryan Dobson
Risk Assessment Reference : RA064	People involved in making this assessment : Ryan Dobson	
Task/ Process : Use of	People at Risk : Employees, Members of the Public, Service Users, Children & Young Persons, Visitors	

Hazard : Confined Spaces People become trapped in the toilet block
Control Measures:
1. Toilet structure, locks etc inspected once a week during cleaning.

Hazard : Fire Wooden structure of toilet or materials within catching fire
Control Measures:
1. No smoking policy across the reserve
2. Refer to Fire Risk Assessment FRA002 for fire prevention across reserve
3. No flammable substances to be stored in the toilet block

Hazard : Infection Infection from toilet waste
Control Measures:
1. Toilets cleaned weekly minimum
2. Hand wash facilities provided at all times

Hazard : Public or Visitor Access Public users causing (accidentally or otherwise) issues with the toilets basic functions
Control Measures:
1. Toilets inspected at least once weekly.
2. Lock on inside of toilet door for use when in use

Hazard : Uneven, Wet or Slippery Floors Slips, trips or falls caused by...
Control Measures:
1. No slip concrete floor

2. Toilet cleaned and inspected once per week minimum

Hazard : Manual handling

Control Measures:

Documents Associated with this Risk Assessment:

Review Date : 11/01/2022	Reviewer : Ryan Dobson
---------------------------------	-------------------------------